Oil Field Environmental Incident Summary

Responsible Party: MUREX PETROLEUM CORPORATION **Well Operator:** MUREX PETROLEUM CORPORATION

Well Name: JOHNSON 24-19

Field Name: NORTH HAAS Well File #: 11120

Date Incident:5/9/2016Time Incident:10:00Facility ID Number:County:BOTTINEAUTwp:163Rng:82Sec:19Qtr:

Location Description: 48.922215 N -101.350432 W 2928 104th St NW Antler ND

Submitted By: William Jansky Received By:

Contact Person: Shannon Holter

363 N. Sam Houston Pkwy. E.

Suite 200

HOUSTON, TX 77060

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building: 500 Feet

Distance Nearest Water Well: Type of Incident: Pipeline Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 5 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

50'x50'

Potential Environmental Impacts:

Possible groundwater contamination.

Action Taken or Planned:

Valve was replaced. Absorbent and safety solutions called to excavate the area. Pipeline will be repaired and pressure tested.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 5/10/2016 Status: Reviewed - Follow-up Required Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained. Further follow-up needed.

Date: 5/19/2016 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 11:55, 5/19/2016.

No sign of impacts at the time of inspection. The area appears to have fresh soil in the area.

No on-site inspection necessary. Contact company for sample results if they have them.